

NEVADA SITE OFFICE

Coal Tar Flaking in Fire Protection Water Supply

Brian Fiscus, P.E.

Coal Tar Flaking in Fire Protection Water Supply

Background:

- Underground steel lead-in piping was installed between a material storage building and the building's water supply source that include a water tank and looped system feeding the lead-in lines.
- Interior surface of underground steel lead-in pipes were treated with a factory-applied, corrosion resistant, coal-tar epoxy coating.
- Coal tar lined lead-in pipes were incorrectly installed (early 1990s).

Coal Tar Flaking in Fire Protection Water Supply

Background (cont'd):

- Instead of mechanical fittings, the installing contractor “field welded” pipe sections together.
- As a result of heat applied during the welding process, the coal-tar epoxy coating was damaged at the joints.
- Coal tar epoxy coating lost its adhesion at the pipe joints and began to flake off.

Coal Tar Flaking in Fire Protection Water Supply

In FY-07 significant increase in coal tar collected during flush
(one strainer/one flush)



Coal Tar Flaking in Fire Protection Water Supply

In FY-07 significant increase in coal tar collected during flush
Cont'd




Coal Tar Flaking in Fire Protection Water Supply

FY 08 and 09 Funded Actions (examples):

- Perform Reliability Analysis
- Strainer Replacement Project
- Coal Tar Study
- Flow Testing
- Gather Results and Determine Needed Approach

Coal Tar Flaking and Corrosion in the Device Assembly Facility Fire Suppression System



2009 DOE/Contractor Fire
Safety Workshop

Glenn Edgemon, NACE CCS
ARES Corporation

Dr. Graham E.C. Bell, PhD, PE
M.J. Schiff & Associates, Inc.

Introduction



- Device Assembly Facility (DAF) fire suppression system:
 - Main 10-in. diameter, mortar-lined, ductile iron header loop.
 - 29 ASTM A106 Sch 40 carbon steel pipes (4-in. or 6-in. diameter) lead-in lines.
- Lead-in lines lined with CTE per ANSI/AWWA C203.
- Particles and flakes of CTE in flush water since startup.
- DNFSB expressed concerns about continuing degradation of the underground lead-in lines.
- ARES Corporation contracted by NSTec to determine:
 - Determine why CTE lining continues to delaminate,
 - Assess corrosion implications of the loss of the lining, and
 - Identify possible solutions for mitigating these issues.

Technical Approach



- Six lines proposed for evaluation:
 - Five 6-in. diameter lines plus Line 712, a 4 in. diameter line.
- Techniques:
 - CTE particle analysis,
 - Lead-in line water analyses,
 - Borescopic videos, and
 - Remote Field Tool (RFT) – remote field eddy current.
- Could not fully investigate all the lines as planned.
 - Unexpected joints and elbows in pipes below DAF floor.
- Collected as much field data as possible.

Inspections

Line	Diameter	RFT Inspection	Borescopic Inspection?	CTE Analysis?	Water Testing?
370-1E	6 in.	Yes	Yes	Yes	Yes
370-1W	6 in.	Yes	Yes	Yes	Yes
712	4 in.	No	Yes	Yes	Yes
494	4 in.	No	Yes	Yes	Yes
492	4 in.	No	Yes	Yes	Yes
711	4 in.	No	Yes	Yes	Yes
491	4 in.	No	Yes	Yes	Yes
301	6 in.	No	No	Yes	Yes
303	6 in.	No	No	Yes	Yes
354	6 in.	No	No	Yes	Yes
352	6 in.	No	No	Yes	Yes
Feed Tank		No	No	N/A	Yes

CTE Particle Analysis



- Analysis of 831 CTE samples collected in 2000 – 2008:
 - Weighed and categorized by line,
 - Visual and microscopic inspections,
 - Lining thickness measurements,
 - Temperature at application, and
 - Comparison with borescopic videos of line interiors.

CTE Particle Analysis (Cont'd)




- Surface profile: ~0.5 mils.
 - AWWA C203: 1.5 to 3.5 mils.
 - No sharp, angular profile on the backs of the samples.
- Piping improperly prepared for application of CTE.
 - Proper surface preparation is critical to adhesion.
- Random chip sampling, 40 to 60 mils in thickness.
 - AWWA C203 recommends 62 to 125 mils.
- Does not meet minimum thickness requirements.
- Lack of corrosion product on the back of many samples.
 - Mechanical stripping, likely due to high flow rates.

CTE Particle Analysis (Cont'd)




- Pipes welded, not flange-fitted.
- Welding damage provides initiation points for delamination.
- Pits/blisters provide new initiation points.
- Lining continues to delaminate once initiated.
 - Poor adhesion + turbulence + viscous forces + corrosion.
- Supported by video: CTE lining loss well away from joints.
- Supported by flow rate data: flushes (<15 ft/sec).
 - Good CTE should withstand ~45 ft/sec.
- Current flushing protocol likely exacerbates delamination.
 - Oxygen for corrosion and high flow rates to strip CTE.

CTE Mass Loss vs. Flush Time



- Mass loss by line varies over four orders of magnitude.
- Generally linear relationship between flush time and mass loss.

Liner Damage at Welds: Line 370-1W, Third Joint (87 ft.)




Delamination: Line 712 (Between DIP & Joint 1)



Delamination:

Line 712 (Between Joints 2 & 3)



Delamination:

Line 491 (Between Joints 5 & 6)



Microbiologically Induced Corrosion

- MIC is simply corrosion accelerated due to microbial activity.
- MIC common in FPS with extended periods of wet or dry lay-up.
- Produces slime (bio-mass) and tubercles...
 - lumpy growths of corrosion products, living/dead cells, and accumulated sediment.
- Tubercles isolate metal surface underneath from bulk solution.
 - Pitting often under tubercles due to isolation.
 - Localized corrosion and rates of metal loss can be high.
- Treatment of the underlying microbes with a biocide difficult.
 - Most treatment relies on contact of the chemicals with living cells.

Water Testing for MIC




- Water tested in each line opened for chlorine and MIC-producing bacteria common to fire suppression systems.
 - Aerobic bacteria
 - Acid-producing bacteria
 - Sulfate-reducing bacteria
 - Iron-related bacteria
 - Low nutrient bacteria
- All lead-in line water samples tested positive for some.
- Tubercles consistent with MIC observed with borescope.
- Residual chlorine levels essentially zero in most lines.

MIC Tubercles:

Line 370-1E, Second Joint (77 ft.)



MIC Tubercles: Line 711, Sixth Joint (114 ft.)



MIC Tubercles:

Line 711, Seventh Joint (131 ft.)



Morphology of MIC




Blistering & Pitting Corrosion



- Blistering of liner due to corrosion.
 - Pits Initiate at holidays/defects in lining.
- Local area caps, fills with corrosion product
 - Differential aeration cell forms to accelerate corrosion
 - Can acidify over time further accelerating corrosion.
- Metal dissolution concentrated in small areas.
- Corrosion can become autocatalytic under cap.
 - Increasingly rapid rates of corrosion.
 - Unresponsive to changes in the bulk water chemistry.

Blistering & Pitting: Line 494 (Downstream of Joint 6)



Blistering & Pitting: Line 711 (Between Joints 3 & 4)



Blistering & Pitting: Line 711 (Between Joints 4 & 5)



Galvanic Corrosion



- Brass Pressure Isolation Valves (PIVs) not electrically isolated from the carbon steel lead-in lines.
- Substantial corrosion noted at the brass/steel intersection.
- Damage confined to steel exposed under the edge of the lining adjacent to the PIV.
- Corrosion in this small area is accelerated by galvanic couple.
- Typically prevented with flange insulation kits.
- No insulating kits were specified or observed.

Galvanic Corrosion: Line 494 PIV/Pipe Intersection



Galvanic Corrosion: Line 370-1W PIV/Pipe Intersection



Wall Thickness: RFT Technique




- RFT: is modification of traditional eddy-current techniques.
- Creates complete map of corrosion damage in pipe wall.
- Inline, water-propelled tool + wireline winch.
- Exciter coil and a circumferential array of detector coils.
- Two coupling paths between the exciter and the detector coils:
 - Eddy currents induced at exciter, pass through wall, along outside wall, then back to detectors...measure “flight time”.
- Anomalies in indirect path change received signal.
- Changes in signal indicate wall thinning/corrosion damage.
- Characterizes both the interior and exterior line surfaces.

RFT Equipment



Example RFT Data: Line 370-1E



RFT Results: Lines 370-1E & 370-1W

370-1E Feature	Max. Wall T Loss (% Nom)
Ductile Iron-to-Steel Flanged Joint	Not Recorded
First Welded Steel Joint	30%
Second Welded Steel Joint	20%
Third Welded Steel Joint	20%
Fourth Welded Steel Joint, End Inspection	Not Recorded

370-1W Feature	Max. Wall T Loss (% Nom)
Ductile Iron-to-Steel Flanged Joint	Not Recorded
First Welded Steel Joint	20%
Second Welded Steel Joint	20%
Third Welded Steel Joint	80%
PIV, End of Inspection	Not Recorded

Other Issues: Cathodic Protection



- There are no CP systems on the DAF lead-in lines.
- Lines coated in CTE and wrapped in Kraft paper prior to burial.
- CP necessary to minimize soil-side corrosion at breaks in coating.
 - Even the best coatings contain holidays from factory.
 - Coatings almost always damaged by handling/backfilling.
 - Shear stresses damage coating as the soil settles.
- Sheer stresses are of particular concern at the DAF.
- Corrosion can be very rapid without the application of CP.
 - High soil resistivities-yes, but gradients in aeration, chloride content, porosity, etc. set up anodes and cathodes on pipe exterior...

Electrical Continuity

- All lead-in lines electrically continuous with DAF:
 - Building ground system
 - Concrete-encased rebar and other concrete-encased steel.
- Not an uncommon problem with fire suppression piping.
- Creates galvanic corrosion cell between the lead-in lines and the copper and/or concrete-encased steel.
- Galvanic cell accelerates corrosion at breaks in coating
 - Both on interior and exterior surfaces.
- Typically prevented with flange insulation kits
- No insulating kits were specified or observed.

Ignored Electrical Continuity



Summary of Inspection Findings



- DAF lead-in lines do not appear to have been properly prepared for CTE lining.
- Delamination is partly mechanical, partly corrosion related.
 - Problem exacerbated by flushing.
- General, MIC, pitting, crevice, and galvanic corrosion are active.
- MIC and pitting present substantial threats to line integrity.
 - Wall thickness loss of 20% and 80% at welded joints.
- Galvanic corrosion at uninsulated PIV/pipe interface.
- No CP.
- Fire piping grounded to building ground systems.

Life Extension



- Reduce line flush rate/periodicity (preserve remaining CTE),
- Pig for deposits (minimize new pitting/crevice corrosion),
- Apply water treatment and corrosion monitoring program,
- Install insulating flange kits (eliminate galvanic cells),
- Install a CP system (minimize external corrosion),
- Inspect balance of system (header loop, internal lines),
- Periodic analysis of biological activity & water chemistry,
- Periodic internal inspection, and
- Eternal vigilance.

Rehabilitation



- Clean/Repair and Treat:
 - Clean/reline and water treat.
 - “Trenchless”, “Repair-in-place” liners, coatings, etc.
 - Becoming more popular...
- Re-plumb/Replace and Treat:
 - Depends on owner’s perspective and risk aversion.
- Run to Failure:
 - Simple, but risky.
 - Most often applied...

Conclusions



- Lining delamination related to:
 - Improper application of liner + corrosion + flushing.
- Lining delamination can be reduced by reducing flushing.
- Corrosion mechanisms are multifaceted; damage is significant.
 - General, MIC, pitting, crevice, and galvanic corrosion are active internally.
 - Lack of CP and building ground issues affecting external degradation.
- Good news: Multiple paths forward...
 - Immediate changes/upgrades can be made to minimize rate of degradation.
 - Longer term rehabilitation options: clean & treat, or repair/replace.

Nevada Site Office Fire Suppression System Actions

- **FY'09 with Carry Over into FY'10:**
 - **Strainer Replacement and FSS Reconfiguration**
 - **Tank Refurbishment**
 - **Stand Alone Units**
 - **Leak Detection**
- **Long term:**
 - **Replace Water Tank and Lead-in Lines (Line Items)**